



1786 Loop Motor Board Circuit



Q3-3904
Q4-3906



Met: Hands moving wick & many loads connected to input and no P.F.
⇒ Change picking to wick!!!

Fast Down Flooder $\Rightarrow$ D15
Fast Up Flooder $\Rightarrow$ D14
Slow Lane Prof $\Rightarrow$ Q5